

# MICCRO SUPER XP-2000<sup>®</sup> STOP-OFF LACQUER



## SUITABLE FOR USE IN THE FOLLOWING CYCLES:

ACID ETCHING • ANODIZING • ANY ACID CYCLE LEAD • NICKEL-ELECTROLESS

# **APPLICATION PROCEDURE**

## MICCRO SUPER XP-2000® SHOULD BE STIRRED PRIOR TO USAGE

- 1. Chemically and/or mechanically clean the area of the part to be masked. The area to be masked must be free of all dirt, grease, or other contaminates. NOTE: Cleaning is the most critical aspect of the masking procedure.
- 2. Apply MICCRO SUPER XP-2000® to the area to be masked by dipping, brushing or spraying. For reducing MICCRO SUPER XP-2000®, use the MICCRO SUPER XP-2000® REDUCER only.
- 3. Two or three coats are recommended depending upon the type of plating/chemical solution and/or length of processing time in solution. Allow at least a one-hour dry time between coats. A longer dry time between coats will improve the performance of the product. This factor is highly dependent on the severity of the plating cycle. Faster drying of MICCRO SUPER XP-2000® can be accomplished by force drying for 15 minutes in an oven. Temperatures must not exceed 140°F and times over 15 minutes. Dry time will vary according to relative humidity. NOTE: Make sure MICCRO SUPER XP-2000® has lost all solvent odor before force drying or applying additional coats. For maximum usage, we suggest an overnight dry before plating.
- 4. For extra long cycles, three coats are recommended. If area to be masked is polished, refer to the "Masking Polished or Highly Smooth Surfaces" technical data page.
- 5. MICCRO SUPER XP-2000® can normally be peeled from the part after processing. For mass stripping or removal from recessed areas, use MICCRO SUPER XP-2000® REDUCER, MICCROSTRIP® A, and MICCRO SAFE-STRIP® C.

# **CHARACTERISTICS**

**Color:** Orange • **Wt./Gal:** 8.0 lbs/gal • **Coverage Rate:** Approximately 130 ft.<sup>2</sup>(12m<sup>2</sup>) per gallon **Viscosity:** 5000-6000 cps • **Flash Point:** 24°F TCC • **Dry film:** 1 mil • **VOC:** 4.8 lbs/gallon

Available in 1 gallon, 5 gallon and 55 gallon containers



220 WEST 5TH STREET, HOPE, ARKANSAS 71801 PH: (870) 777-3251 • FAX: (870) 777-8056 • www.TOLBER.com